

OHIO EPA DHHM

AUG 14 2008

OGM Ltd. dba Clean Water Ltd.
HW Permit Renewal and Class 3 Permit Modification
Page 28 of 41

The Permittee must store in containers only the hazardous waste codes specified below:

D001, D004, D005, D006, D007, D008, D009, D010, D011, D018, D019, D021, D022, D023, D024, D025, D026, D027, D028, D029, D034, D035, D036, D038, D039, D040, D043;

F001, F002, F003, F004, F005, F037, F038;

K048, K049, K050, K051, K052, K087;

U002, U019, U031, U037, U052, U056, U057, U070, U071, U072, U080, U112, U117, U121, U140, U154, U159, U161, U171, U196, U210, U211, U220, U226, U227, U228, U239.